

IF THE PAGE FILMED IS NOT  
AS LEGIBLE AS THIS LABEL,  
IT IS DUE TO THE QUALITY  
OF THE ORIGINAL.

EPA POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION		REGION 06	SITE NUMBER LA0981910656
NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.			
A. SITE NAME Amoco #1 <i>Phoebe</i>		B. STREET (or other identifier) 0.7 mi. North of LA Hwy 390 and 0.3 mi. West of Hwy 27.	
C. CITY Hackberry	D. STATE LA	E. ZIP CODE 70643	F. COUNTY NAME Cameron 023
G. OWNER/OPERATOR (if known) J.L. Bonner P.O. BOX 660, Tyler, Tx 75710		2. TELEPHONE NUMBER	
H. TYPE OF OWNERSHIP (if known) <input type="checkbox"/> 1. FEDERAL <input type="checkbox"/> 2. STATE <input type="checkbox"/> 3. COUNTY <input type="checkbox"/> 4. MUNICIPAL <input checked="" type="checkbox"/> 5. PRIVATE <input type="checkbox"/> 6. UNKNOWN			
I. SITE DESCRIPTION 29°59'48"N 93°22'27"W 0.6 acre site is a petroleum production and separating facility with five oil storage tanks and three separating units. See "CAM 57", Browns Lake topo map			
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) Aerial photographs and FIT windshield survey		K. DATE IDENTIFIED (mo., day, & yr.) 2-17-87	
L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM Desalinization ponds, containing oily waste, were leaking. Oily residue was observed throughout the site.			
M. PREPARER INFORMATION 1. NAME R. David Shiels/Jo Ann T. Weber		2. TELEPHONE NUMBER (214) 742-6601	3. DATE (mo., day, & yr.) 2-23-87

SUPERFUND  
FILE

JUL 17 1992

REORGANIZED

Reviewed by SPES  
Date 2/24/87

IF THE PAGE FILMED IS NOT  
AS LEGIBLE AS THIS LABEL,  
IT IS DUE TO THE QUALITY  
OF THE ORIGINAL.

BROWNS LAKE QUADRANGLE  
LOUISIANA-CAMERON PARISH  
7.5 MINUTE SERIES ORTHOPHOTOMAP (TOPOGRAPHIC)  
NW/4 CAMERON 15' QUADRANGLE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

